TOYOTA

Technical Service BULLETIN

June 5, 2006

Title:

EXCESSIVE SULFUR ODOR

Models:

'07 Yaris Liftback

TSB

ENGINE

REVISED

EG035-06

TSB REVISION NOTICE:

- **August 4, 2006: Applicable vehicles have been clarified — This TSB applies ONLY to Yaris Liftback models.**

Previous versions of this TSB should be discarded.

Introduction

Some customers may complain of excessive sulfur odor on 2007 model year Yaris vehicles under the following conditions:

- Stop and go driving
- Heavy acceleration

In order to reduce the sulfur odor, a new front catalytic converter has been made available. Follow the repair procedure to replace the catalytic converter assembly.

Applicable Vehicles

- **2007** model year **Yaris Liftback** vehicles.

Parts Information

ORIGINAL PART NUMBER*	REPAIR PART NUMBER*	PART NAME	QTY
17410–21540	17410–21800	Pipe Assembly, Exhaust, Front	1

*** NOTE:**

The original part number (17410–21540) is currently used in vehicle production and is still available as a service part. The repair part number (17410–21800) should ONLY be used when the customer complains of sulfur odor.

Repair Procedure

Refer to the Technical Information System (TIS), 2007 model year Yaris Repair Manual: *Exhaust: Exhaust Pipe Assy (1NZ–FE).*

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
170171	R & R Front Exhaust Pipe Assembly	0.5	17410–21540	60	99

Applicable Warranty:**

This repair is covered under the Toyota Specified Major Emission Control Component Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicle's in-service date.

** Warranty application is limited to correction of a problem based upon a customer's specific complaint.